


ADJACENT PROPERTY LINE  
COMBINATION INLET  
CURB  
CURB CUT  
CONTOUR LINE  
DOUBLE DRAIN INLET  
DRAIN INLET  
FENCE  
FENCE POST  
GAS VALVE  
GUY WIRE  
HYDRANT  
MANHOLE  
OIL FILL  
OIL VENT PIPE  
OUTLET CONTROL STRUCTURE  
OVERHEAD WIRE  
PROPERTY CORNER  
PROPERTY LINE  
ROOF OVER  
SANITARY SEWER MANHOLE  
SIGN  
SPOT GRADE  
STONE WALL  
TELECOMMUNICATIONS MANHOLE  
UTILITY POLE  
UTILITY POLE WITH LIGHT  
WALL  
WATER VALVE

|       |                          |
|-------|--------------------------|
| BC    | BOTTOM OF CURB           |
| BWL   | BOTTOM OF WALL           |
| CONC  | CONCRETE                 |
| FFE   | FINISHED FLOOR ELEVATION |
| FNC   | CHAIN LINK FENCE         |
| FNS   | STOCKADE FENCE           |
| FNPVC | POLYVINYL CHLORIDE FENCE |
| GFE   | GARAGE FLOOR ELEVATION   |
| RMS   | REMAINS                  |
| RO    | ROOF OVER                |
| TC    | TOP OF CURB              |
| THRS  | THRESHOLD                |
| TWL   | TOP OF WALL              |



*Previous Editions Obsolete*

- 1) THIS MAP IS BASED ON A FIELD SURVEY COMPLETED ON SEPTEMBER 12, 2018. UTILITIES WERE SURVEYED ON JULY 2, 2019.
- 2) THE PROPERTY LINE SHOWN HEREON IS AS SHOWN ON A MAP TITLED "SURVEY OF PROPERTY" DATED NOVEMBER 29, 2018 AND PREPARED BY JMC PLANNING, ENGINEERING, LANDSCAPE ARCHITECTURE & LAND SURVEYING, PLLC.
- 3) CONTOUR INTERVAL IS (2) TWO FOOT. VERTICAL DATUM IS REFERENCED TO NAVD 1988 WHICH WAS OBTAINED BY GPS METHODS.
- 4) THE LOCATION OR COMPLETENESS OF UNDERGROUND INFORMATION CANNOT BE GUARANTEED. VERIFY THE ACTUAL LOCATION OF ALL UTILITIES PRIOR TO EXCAVATION OR CONSTRUCTION. SUBSURFACE UTILITY LOCATIONS ARE BASED ON A COMPILEATION OF FIELD EVIDENCE AND A UTILITY MARK OUT COMPLETED BY RSR UTILITY MARKOUT SERVICES, INC.
- 5) UNAUTHORIZED ALTERATION OR ADDITION TO A MAP BEARING THE SEAL OF A PROFESSIONAL ENGINEER OR A LICENSED LAND SURVEYOR IS A VIOLATION OF SECTION 7209 OF THE NEW YORK STATE EDUCATION LAW, EXCEPT AS PER SECTION 7209, SUB-DIVISION 2.
- 6) ONLY COPIES FROM THE ORIGINAL OF THIS SURVEY, MARKED WITH AN ORIGINAL OF THE LAND SURVEYOR'S EMBOSSED SEAL SHALL BE CONSIDERED TO BE VALID TRUE COPIES. UNAUTHORIZED REPRODUCTION OF THIS MAP IS A VIOLATION APPLICABLE LAWS.

TO MY KNOWLEDGE AND BELIEF, THIS MAP IS SUBSTANTIALLY CORRECT AS NOTED HEREON.

THOMAS M. SCHMIDT NYS LICENSE NO. 50221

DATE \_\_\_\_\_

COPYRIGHT © 2019 BY JMC


**John Meyer Consulting, Inc.**  
**220 BEDFORD ROAD • ARMONK, NY 10504**  
**voice 914.273.5225 • fax 914.273.2102**

**www.jmcpllc.com**



BEACON COMMONS

16 WEST MAIN STREET  
CITY OF BEACON, DUTCHESS COUNTY, NEW YORK



TS-1